

© 2006 Mazda Motor of America, Inc.

<b>Subject:</b>  DIFFERENTIAL OIL LEVEL - SERVICE TIP	<b>Bulletin No:</b> 03-003/06
	<b>Last Issued:</b> 6/16/2006

## APPLICABLE MODEL(S)/VINS

2006 MX-5

## DESCRIPTION

Differential oil does not leak from the fill plug hole when checking oil level. This is not a cause for concern. During production, each vehicle is filled with 24 oz. (0.7L) of fluid (+/- 3.4 oz. (0.1L)). This calculates to approximately 12 mm from the oil fill plug hole.

### NOTE:

- Damage to the vehicle will not occur if the oil level is topped off to the oil fill plug hole.

