Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



© 2010 Mazda Motor of America, Inc.

Subject:

ESTABLISHMENT OF IGNITION KEY KNOB BASE

Last Issued: 03/30/2010

APPLICABLE MODEL(S)/VINS

2009-2010 MX-5 vehicles with advanced keyless entry system

2009-2010 RX-8 vehicles with advanced keyless entry system

2009-2010 Mazda3 vehicles with advanced keyless entry system


2009-2010 Mazda6 vehicles with advanced keyless entry system

2009-2010 CX-7 vehicles with advanced keyless entry system

2009-2010 CX-9 vehicles with advanced keyless entry system

DESCRIPTION

If it is necessary to replace ignition key cylinder components, be aware that the knob base (A) has been established as a new service part. Use the knob base part instead of replacing the entire key cylinder assembly.



PART(S) INFORMATION

Part Number	Part Name
D6Y1-76-142	Knob Base

Page 1 of 1

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing.