

Service Information

Mazda Motor Corporation

3-1, Shinchi, Fuchu-cho, Aki-gun
Hiroshima 730-8670, Japan
TEL : 81(82)287-5323
FAX : 81(82)287-5220



Category F	Technical	Ref. No. E011/15	Page 1 of 2
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued July 8, 2015	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised	
Applicable Model MX-5(ND)		Applicable Countries or Specifications Worldwide	


Subject: Abolishment of High Pressure Fuel Pipe Cover

DESCRIPTION

To improve serviceability, the high pressure fuel pipe cover (Part No.: P51B-13-2KE) has been abolished.

Although the high pressure fuel pipe cover is specified by the workshop manual as a replacement part, it is not necessary to install the new part during the high pressure fuel pipe removal and installation because it will not affect the performance and quality without the cover.

The workshop manual will be updated.



BEGINNING VIN & DATE OF MODIFICATION

Spec.	Beginning VIN	Date of Modification
ADR	JM0 ND **** ** 100139	June 15, 2015
General	JM6 ND **** ** 100023	
	JM7 ND **** ** 100058	
Israel	JMZ ND **** ** 100058	
EC	JMZ ND **** ** 101303	
US	JM1 ND **** ** 102088	

Ryu Shimizugawa
Manager, Technical Information Gr.
Technical Service Dept.
Mazda Motor Corporation
(MC Internal Use)